

Instructions on how to use:

- 1- Turn all switches "ON"
- 2- For first batch only, let kettle heat for about 4 minutes
- 3- Add oil or oil bar, the cup of corn with FLAVACOL in it
- 4- Dump when popping is about 99% completed
- 5- Repeat steps 3 & 4, always pop at least (5) batches each time you pop.
- 6- ON FINAL BATCH ONLY – Turn the kettle heat OFF as soon as corn starts popping rapidly (to raise kettle lid).

WARNING : Keep kettle switch "OFF" when no popping..

***ALL OF THESE INSTRUCTIONS ARE ALSO WRITTEN ON MACHINE!

This is the type of popcorn you will need to buy for the machine:

